

Weberjets.com - Home of Weber Carburetors

Weberjets.com

92.1154.05 DCNF Repair Kit

\$49.95

DCNF Repair kit. Fits 40, 42, 44 DCNF with 4 and 5 hole top covers. Comes with 2 types of top cover gasket depending on carburetor model, gaskets, o-rings and needle valve.

[Vendor Information](#)

Customer Reviews: There are yet no reviews for this product.
Please log in to write a review.